

## Under Review Notification

**Raised By:** VANESSA MOREL

**Product #:** DART TOOLING FIRE SCOUT

**Date:** 17.10.20

**Product Name:** DRAIN TOOL TAIL ROTOR GEAR BOX

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	PP Under Review	Product Specifications Under Review ("Bluefiles")		
RBT18650-101-1	RBT18650-101 REV A	Y	Y	N	Y	Y	Y	N	17-660	Rework to prelim new drawing or scrap
RBT18650-101-2	RBT18650-101 REV A	Y	Y	N	Y	N	Y	N	17-660	Use prelim new drawing or scrap

**Description of Issue:** FIT ISSUE

RBT18650-101-1 REV B: WAS 0.120" +/-0.005" IS 0.120" +0/-0.005", WAS 0.420" IS 0.420" +0.005"/-0, WAS 0.250" DIA. DEPTH 2.00" IS 0.25" DIA DEPTH 1.812"

RBT18650-101-2 REV B: PART # -2 SHOULD BE -5

**Distribution:**

VP Operations Director of Operations Director Quality Assurance Director of Engineering	Chief Engineer Engineering Project Managers Engineering Clerk Customer Support Manager	Production Engineers Production Planners Purchasing Manager Technical Support	Product Manager - Solutions Provider
--	---	--	--------------------------------------